



Step #1




1. APPLY QUICKSEAM TO THE FLASHING AREA.
2. FOLD THE QUICKSEAM CORNER FLASHING IN HALF SO THAT THE PERFORATED EDGES IS ON THE BOTTOM.
3. REMOVE THE SMALLER HALF OF THE RELEASE PAPER FROM THE OUTSIDE CORNER AND PLACE AGAINST VERTICAL FLASHING AS SHOWN.
4. PLACE THE RELEASE PAPER BETWEEN THE FOLDED FLASHING TO KEEP FLASHING FROM STICKING. THIS WILL AID IN STEPS 3 AND 4.

Step #2



1. STARTING FROM THE VERTICAL CENTER, MOLD EACH SIDE OF THE QUICKSEAM CORNER FLASHING AROUND THE CORNER.


Step #3



1. REMOVE THE RELEASE PAPER FROM THE QUICKSEAM CORNER FLASHING.
2. PLACE YOUR HANDS ON THE FLASHING, PUSHING DOWN UNTIL THE FLASHING EXTENDS 1" (25.4 MM) ONTO GEOMEMBRANE SURFACE, AND TIGHTLY INTO THE 90° BREAK

DURING COOL WEATHER CONDITIONS (60° F (16°C) OR BELOW) USE A HEAT GUN TO ASSIST FORMING OF THE QUICKSEAM CORNER FLASHING.

Step #4



1. WITH A SILICONE COATED RUBBER ROLLER, ROLL THE QUICKSEAM CORNER FLASHING.
2. APPLY CONTINUOUS SEAM EDGE TREATMENT AROUND THE QUICKSEAM CORNER FLASHING AND EXTEND IT 3" (76.2 MM) BEYOND THE EDGE OF THE FLASHING. REFER TO DETAIL S-3.

"THIS PROCESS IS COVERED BY U.S. PATENT 5,520,761"

MAXIMUM WARRANTY: **N/A**

OUTSIDE CORNER USING QUICKSEAM CORNER FLASHING

ISSUE / REVISION DATE:

7-28-2015

DETAIL NO.

C-1

GEOGARD™

Living In Action™



ACCEPTABLE SYSTEMS:

EPDM, EPDM-R, ECOWHITE EPDM

NOT TO SCALE