



Step #1




1. APPLY QUICKPRIME TO AN AREA THAT WILL BE FLASHED WITH QUICKSEAM FLASHING, USING QUICKSCRUBBER PAD AND HANDLE.
2. FOLD CORNER FLASHING TIGHTLY INTO THE CORNER.

Step #2




1. REMOVE THE RELEASE PAPER FROM THE OTHER HALF OF THE QUICKSEAM CORNER FLASHING.
2. MOLD THE CORNER FLASHING TIGHTLY INTO THE VERTICAL, FORMING A PIG-EAR AS SHOWN ABOVE
3. APPLY QUICKPRIME TO THE AREA THAT WILL BE COVERED BY THE PIG-EAR, USING THE QUICKSCRUBBER TOOL. KEEP PIG EAR OPPOSITE THE VERTICAL SEAM.

Step #4



"THIS PROCESS IS COVERED BY U.S. PATENT 5,520,761"

1. ALLOW THE QUICKSEAM PRIMER TO DRY BEFORE PROCEEDING.
2. MOLD THE PIG-EAR TIGHT INTO CORNER AND TO THE WALL AS SHOWN ABOVE.



- NOTE:
1. APPLY CONTINUOUS SEAM EDGE TREATMENT AROUND THE QUICKSEAM CORNER, QUICKSEAM FLASHING, AND TO THE SEAM EDGE OF THE GEOMEMBRANE. REFER TO DETAIL S-3.
  2. DURING COOL WEATHER CONDITIONS ( 60° F (18°C) OR BELOW ) USE A HEAT GUN TO ASSIST FORMING OF THE QUICKSEAM CORNER FLASHING.

MAXIMUM WARRANTY: **N/A**

**INSIDE CORNER USING QUICKSEAM CORNER FLASHING**

GEOGARD™

ACCEPTABLE SYSTEMS:

EPDM, EPDM-R, ECOWHITE EPDM

ISSUE / REVISION DATE:

7-28-2015

DETAIL NO.

C-2



Lining In Action™